



NOTES:

1. LOCATE TRACER ON UNDER SIDE OF PIPING.
2. INSTALL THE TRACER SNUG AGAINST VALVE AND PIPING.
3. DO NOT INSTALL INSULATION BETWEEN THE TRACER AND THE VALVES OR PIPING.

0	ISSUED FOR CONSTRUCTION					
REV	REVISION	DATE	DRN	CHK	ENG	APP
CLIENT	TITLE					
	GLYCOL TRACING CONTROL SET DETAILS					
PREPARED BY	SCALE	DWG. No.	GT-018	PROJ.	REV.	
	N.T.S.	CLIENT			0	
		DWG. No.				